

PART A DELETE FORM

ID # KYD 006 386 403 FACILITY NAME General Electric

F1 Date Part A received: S F6 Drawings: S Photos: S

F8 Facility status: S Existence date: S Permit Status 6

F2 Non-reg. fac. indic.:     

F8 Activity codes: Gen      Trans      TSD S UIC     

Transport mode: Air      Rail      Hwy      Water      Other     

C1 PROCESS CODE:

501

RCRA MAINTENANCE FORM

ID # KyD 006 386 403

FACILITY NAME General Electric

F1 Notif. approval \_\_\_\_\_  
 Date notified \_\_\_\_\_  
 Permit app. approved \_\_\_\_\_  
 Date Part A r'cvd ✓ \_\_\_\_\_  
 \* Facility name \_\_\_\_\_  
 Notif. confidential \_\_\_\_\_  
 Part A confidential \_\_\_\_\_  
 Closure date \_\_\_\_\_

F2 Contact name & title \_\_\_\_\_  
 Contact telephone # \_\_\_\_\_  
 Modif. under const. \_\_\_\_\_  
 Commercial fac. indic. \_\_\_\_\_  
 Non-reg. fac. indic. \_\_\_\_\_

F3 Mailing address \_\_\_\_\_

F4 Mailing city \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

F5 \* Facility address \_\_\_\_\_  
 \* County name \_\_\_\_\_

F6 \* Facility city \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_  
 \* County code \_\_\_\_\_

Drawings to Photos ✓ District code \_\_\_\_\_  
 River basin code \_\_\_\_\_ Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

F7 SIC \_\_\_\_\_ NEW SIC \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

F8 Facility operator name \_\_\_\_\_ Owner type \_\_\_\_\_  
 Activity codes: Gen \_\_\_\_\_ Trans \_\_\_\_\_ TSD ✓ UIC \_\_\_\_\_  
 Transport mode: Air \_\_\_\_\_ Rail \_\_\_\_\_ Hwy \_\_\_\_\_ Water \_\_\_\_\_ Other \_\_\_\_\_  
 Owner/oper ind. \_\_\_\_\_ Facility status ✓ RCRA permit status \_\_\_\_\_  
 Existence date ✓ \_\_\_\_\_

F9 Type Permit number Type New permit number  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

(over)

F0 Date acknowledgement sent: Notification \_\_\_\_\_  
 Int. status \_\_\_\_\_ Int. status 2 \_\_\_\_\_  
 FA Operator tele. # \_\_\_\_\_ Street \_\_\_\_\_  
 FB City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Indian land \_\_\_\_\_  
 FC Comment # \_\_\_\_\_ Comment \_\_\_\_\_  
 FE Facility owner \_\_\_\_\_ Tele.# \_\_\_\_\_  
 FF Owner street \_\_\_\_\_  
 FG Owner city \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

C1	Process code	Amount	Unit	New code	New Amount	New Unit
	501	_____	_____	<del>1</del>	_____	_____
	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____

W1	Waste seq #	Waste Code	Waste Amount	Unit	New Waste	New Amount	New Unit
	_____	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____	_____
	_____	_____	_____	_____	_____	_____	_____

W2	Waste Seq #	Waste Code	Process	Change Process
	_____	_____	_____	_____
	_____	_____	_____	_____
	_____	_____	_____	_____
	_____	_____	_____	_____
	_____	_____	_____	_____

September 23, 1982

Mr. A.C. Bayer, Manager  
Manufacturing Engineer  
General Electric Company  
1801 G.E. Drive  
Lexington, Kentucky 40503

RE: EPA I.D. KYD00-638-6403

Dear Mr. Bayer:

The Division of Waste Management, acting under RCRA Phase I Interim Authorization (as published in the April 1, 1981, Federal Register), is withdrawing your U.S. EPA form 3510-1 known as the Federal Hazardous Waste Facility permit application part "A". The U.S. EPA has determined that your company can terminate their interim status as a storage facility without complying with 40 CFR Part 265 Subparts G and H, provided they continue to use the area for storage of hazardous waste which will be removed within the 90 day limit and are in compliance with 40 CFR 262.34. If your company no longer intends to use the area for storage of hazardous wastes, it must be closed in accordance with 40 CFR Part 265 Subpart G and H.

If you have any questions on this, please contact James A. Determann of this office at (502) 564-6716, Ext. 248.

Sincerely,



J. Alex Barber, Director  
Division of Waste Management

JAB:JAD:cg

cc: James H. Scarbrough, U.S. EPA  
Field Supervisor



DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
BUREAU OF ENVIRONMENTAL PROTECTION  
FEDERAL BUILDING PLAZA  
WASHINGTON, D.C. 20500

August 30, 1982

Mr. James H. Scarbrough, Chief  
Residuals Management Branch  
U.S. EPA Region IV  
345 Courtland Street, N.E.  
Atlanta, Georgia 30365

Dear Mr. Scarbrough:

This letter is in response to your request for recommendations concerning companies which might be eligible to receive an interim status compliance letter. An initial review of these facilities was performed from the central office files. The results from this review were sent to the field offices for verification. Attached you will find a summary of the findings and recommendations.

If you have any questions, please feel free to contact James Determann of this office at (502) 564-6716, Ext. 248.

Sincerely,



J. Alex Barber, Director  
Division of Waste Management

JAB:JAD:cg

cc: Field Office  
Pat Haight, Compliance Branch

Mr. Harry Russell  
The Tappan Company  
East Main Street  
Murray, Kentucky 42071  
KYD00-636-6918 - This facility is closed.

Mr. Ken Weems  
Univar Van Waters & Rogers Div.  
2000 S. 9th Street  
Louisville, Kentucky 40208  
KYD02-407-1433 - The company is not a facility, only a transporter. Kentucky does not recommend an ISCL.

Mr. Jim Johnson  
Roe Creek Development  
P.O. Box 655  
Catlettsburg, Kentucky 41129  
KYD99-127-7005 - This facility is accepting a waste which is being tested to determine if it is hazardous. They are presently in violation of interim status standards. They have expressed an interest in withdrawing if it is determined that the waste is non-hazardous. Kentucky recommends ISCL be issued.

Mr. William Snedegar  
Resource Conservation Recovery Systems, Inc.  
Henry County Incinerator  
865 King Avenue  
Columbus, Ohio 43212  
KYD98-060-1298 - A partially constructed incinerator exists at this site. Construction started after November 19, 1980 and the State notified the company of violation and to cease construction. Since the site was not "in existence" Kentucky does not recommend an ISCL.

Mr. Butch Rosenbaum  
Rail Services, Inc.  
P.O. Box 35  
Calvert City, Kentucky 42029  
KYD99-127-6833 - A letter was sent to you June 4, 1982, requesting that an ISCL be issued to the company.

Mr. Robert M. Rasmuson  
The Okonite Company  
P.O. Drawer "L"  
Richmond, Kentucky 40475  
KYD04-753-7824 - A letter was sent to you June 21, 1982, requesting that an ISCL be issued to this company.

Mr. Steve Vinson  
Simmons (National) Casket Company  
P.O. Box 42  
Lancaster, Kentucky 40446  
KYD05-007-4889 - This company is not a hazardous waste storage facility, as they store less than ninety (90) days. Kentucky does not recommend an ISCL.

Mr. A.S. Dennison  
LG & E Trimble County  
P.O. Box 32010  
Louisville, Kentucky 40232

KYD99-127-7096 - This company requested withdrawal of their Part A in a July 19, 1982 letter to EPA. This site is presently under construction and has never been used as a hazardous waste facility, therefore no ISCL is necessary.

Mr. Daniel R. Conkey  
Mobile Tank Car Services  
P.O. Box 37300  
Louisville, Kentucky 40233

KYD00-061-6375 - We are presently working with this company to determine if they need and/or qualify for an ISCL. A separate recommendation will follow.

Mr. Robert W. Anderson  
McKesson Chemical Company  
600 Hunter Drive  
Oak Brook, Illinois 60521

KYD04-259-3368 - No field verification to date. A separate recommendation will follow.

Mr. Shird Robinson  
L G & S Disposal  
7500 Grade Lane  
Louisville, Kentucky 40219

KYD00-083-1016 - This facility never received a construction permit due to their inability to get proper zoning. Kentucky does not recommend an ISCL.

Mr. William M. Walthen  
Heublein, Inc.  
500 Charter Oak Drive  
Paducah, Kentucky 42001

KYD09-151-5502 - This company is a small quantity generator. They generate waste ethyl alcohol and incinerate it on site. No ISCL is needed.

Mr. Ron Hanscrote  
Goodyear Tire & Rubber Company  
P.O. Box 589  
Madisonville, Kentucky 42431

KYD04-116-6893 - We withdrew this company's part A on July 9, 1982.

Mr. Robert Brunson  
Newport Steel Corporation  
Ninth & Lowell Streets  
Newport, Kentucky 41072

KYD99-127-7112 - This facility should have interim status. They assumed ownership and began operating the former Interlake Steel Operation April 20, 1981. Interlake Steel had interim status for their hazardous waste landfill at that time. Henry L. Steven's letters to Howard Zeller (EPA) June 2, 1981, and Keith Casto (EPA) June 5, 1981, reference agreements between Kentucky, U.S. EPA and Newport Steel. They submitted a revised notification and Part A on June 30, 1981.

Mr. A.C. Bayer  
G.E. Lexington Lamp Plant  
1801 General Electric Drive  
Lexington, Kentucky 40503  
KYD00-638-6403 - This company has container storage. However, they do not store their waste over 90 days and do not need an ISCL.

Mr. Dale E. Harstine  
G.E. Lexington Glass Plant  
P.O. Box 1519  
Lexington, Kentucky 40591  
KYD00-638-6395 - This company is not a hazardous waste TSD waste facility. They made a protective filing and do not need an ISCL.

Mr. Wayne Dawson  
GMC Whs. & Dist. Div.  
6060 W. Bristol Road  
Flint, Michigan 48554  
KYD06-833-5231 - This company has submitted a withdrawal request which is being reviewed. Kentucky will copy EPA when a determination is made.

Mr. Ray Fox  
Midsouth Electric, Inc.  
Route 6, Box 400  
Manchester, Kentucky 40962  
KYD00-023-9293 - No field verification to date. A separate recommendation will follow.

Mr. Cecil Iglehart, P.E.  
SCA Services of Kentucky  
(Central Fill, Inc.)  
P.O. Box 34457  
Louisville, Kentucky 40232  
KYD99-127-7104 - We withdrew this facility's Part A on August 3, 1982.

Mr. Ray Daniels  
Ashland Chemical Company  
P.O. Box 391  
Ashland, Kentucky 41101  
KYD00-082-8806 - A letter was sent to you June 21, 1982, requesting that an ISCL be issued to this company.

Ashland Chemical Company  
4185 Algonquin Parkway  
Louisville, Kentucky 40211  
KYD02-404-1063 - A letter was sent to you June 21, 1982, requesting that an ISCL be issued to this company.

Mr. Gene Sigler  
Anaconda Aluminum Sebree  
P.O. Box 44  
Henderson, Kentucky 42420  
KYD05-369-2521 - Spent Cathode Liners (K088) landfilled at this facility. Been suspended temporarily from 40 CFR 261.32 hazardous waste listing.



16, 1981). Therefore, the landfill does not accept hazardous waste and does not need interim status.

Mr. J.B. Whitaker  
American Standard  
WABCO Fluid Power  
1953 Mercer Road  
Lexington, Kentucky

KYD00-639-8002 - This company is a small quantity generator, and not a storage facility. Therefore, no interim status is necessary.

Mr. James Kearns  
American Printing House for the Blind  
1839 Frankfort Avenue  
Louisville, Kentucky 40206

KYD00-637-4532 - We are presently reviewing and verifying a withdrawal request for this facility. Kentucky will copy EPA when a determination is made.

Mr. Jackie Steele  
American Greetings Corp.  
R.F.D. 3  
Corbin, Kentucky 40701

KYD04-573-9471 - No field verification to date. A separate recommendation will follow.

Mr. R.M. Gaudiano  
Amax Ayrgem Mine  
105 South Meridian Street  
Indianapolis, Indiana 46225

KYD00-077-3382 - We are presently reviewing and verifying a withdrawal request from this company. This site is closing and indications are that this was not a hazardous waste facility and interim status is not needed.

Mr. Bill Antrobus  
A.A. Brown, Inc.  
337 Green Road  
Walton, Kentucky 41094

KYD02-419-9929 - This company was a hazardous waste recycler and is now closed. No interim status is needed.

Mr. Douglas Ramey  
B-T Energy Corporation  
15700 Dixie Highway  
Louisville, Kentucky 40272

KYD07-966-1146 - This company is a hazardous waste facility and they are working with us to obtain an ISCL.

Mr. Gil Lovell  
Barret of Kentucky  
P.O. Box 316  
Campbellsburg, Kentucky 40011

KYD08-239-1012 - This company's waste was declared non-hazardous due to the lack of test for reactivity. No interim status is necessary.

Mr. Shird Robinson  
Campground Fill, Inc.  
7500 Grade Lane  
Louisville, Kentucky 40219  
KYD09-895-1262 - We are withdrawing this landfill's Part A. EPA will be copied when the determination is final.

Mr. Mark Love  
Ceramichrome, Inc.  
P.O. Box 327  
Stanford, Kentucky 40484  
KYD06-764-6737 - This company is a hazardous waste facility and is in compliance with interim status standards. An ISCL should be issued.

Mr. Donald R. Eaton  
Cumberland Wood & Chair Corporation  
P.O. Box 691  
Somerset, Kentucky 41501  
KYD00-636-5589 - This company is a hazardous waste facility and is working with Kentucky to obtain an ISCL or close.

Mr. Larry Reeves  
Deena Products, Inc.  
P.O. Box 158  
Arlington, Kentucky 42021  
KYD05-682-7215 - This company is a small quantity generator not a storage facility and does not need interim status.

Mr. Paul N. LaVertu  
Derby Tank Car Mfg.  
P.O. Box 38  
Ekron, Kentucky 40117  
KYD07-406-9543 - This company is not a hazardous waste storage facility and does not need interim status.

Mr. Larry R. Adams  
Eaton Corporation  
New Lair Road  
Cynthiana, Kentucky 41031  
KYD09-390-3862 - This company has a hazardous waste surface impoundment and is in compliance with interim status standards and should be issued an ISCL.





UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IV

345 COURTLAND STREET  
ATLANTA, GEORGIA 30365

SEP 17 1982

AW-RM

Mr. A. C. Bayer, Manager  
Manufacturing Engineering  
General Electric Company  
1801 GE Drive  
Lexington, KY 40503

Re: Request for Withdrawal of EPA Hazardous Waste Application  
EPA I.D. No. KYD006386403

Dear Mr. Bayer:

This letter is to acknowledge receipt of your request for withdrawal of your application for a permit under the Resource Conservation and Recovery Act (RCRA), as amended. Your letter indicated that you no longer treat, store, or dispose of hazardous waste.

Withdrawal of your permit application constitutes revocation of interim status, as defined by §3005(e) of the Act. Consequently, under the Federal program, you would no longer be allowed to treat, store, or dispose of hazardous waste. However, as you are probably aware, the State has been authorized to implement certain requirements of the program in lieu of the Federal regulatory requirements. Therefore, withdrawal of your application also directly affects the State program.

In light of the foregoing, EPA plans to proceed as follows. EPA will place your file in our "suspense" file. This action, in essence, revokes your interim status under the Federal program. However, we will forward the request to the State for formal action. The State will contact you if further information relating to your request is required. If the State agrees that you do not need a RCRA permit, they will notify you of this determination, and by carbon copy of this notification sent to EPA, your application will be formally withdrawn, and your file will be inactivated.

The RCRA Hazardous Waste Regulations (40 CFR §265.112) require that an owner or operator of a hazardous waste facility submit his closure plan to the Director of the State Hazardous Waste Agency within 15 days after the termination of interim status. This is the first step in the initiation of closure procedures required under 40 CFR §§265.110 to 265.120. Each of the

states in Region IV of EPA has substantially equivalent state regulations. By copy of this letter we are notifying the State Hazardous Waste Agency that all regulatory requirements for closure of your hazardous waste facility should be met and documented in their files.

If your facility is a generator who will continue to accumulate hazardous waste for short periods of time (less than 90 days) prior to shipment off site you should be aware of the hazardous waste regulations which apply to generators who accumulate hazardous waste. In the Federal program these regulations are found in 40 CFR §262.34.

In conclusion, this letter should not be construed as EPA's concurrence with your determination that RCRA regulatory requirements are not applicable to your facility. Furthermore, this letter does not relieve you of your responsibility to comply with State and local hazardous waste regulatory requirements.

Finally, your request to withdraw interim status means that you may not treat, store, or dispose of hazardous waste without a permit issued under the authority of §3005 of the Act and 40 CFR Part 264.

If you wish to reconsider this withdrawal request, please advise this office and the State within the next ten days. You should be receiving a formal response to your request from the State in the near future.

If you require further clarification, please contact Doug McCurry of the Waste Engineering Section (404) 881-3433 or a representative of the State Hazardous Waste Program.

Sincerely yours,

James H. Scarbrough, Chief  
Residuals Management Branch  
Air & Waste Management Division

cc: Kentucky Department for Natural Resources  
and Environmental Protection.



FORM 1 GENERAL U.S. ENVIRONMENTAL PROTECTION AGENCY GENERAL INFORMATION Consolidated Permits Program (Read the "General Instructions" before starting.) I. EPA I.D. NUMBER KYD 006 386 403 T/A C D F 1 2 13 14 15

III. FACILITY NAME

V. FACILITY MAILING ADDRESS

VI. FACILITY LOCATION

PLEASE PLACE LABEL IN THIS SPACE

GENERAL INSTRUCTIONS

If a preprinted label has been provided, affix it in the designated space. Review the information carefully; if any of it is incorrect, cross through it and enter the correct data in the appropriate fill-in area below. Also, if any of the preprinted data is absent (the area to the left of the label space lists the information that should appear), please provide it in the proper fill-in area(s) below. If the label is complete and correct, you need not complete items I, III, V, and VI (except VI-B which must be completed regardless). Complete all items if no label has been provided. Refer to the instructions for detailed item descriptions and for the legal authorizations under which this data is collected.

II. POLLUTANT CHARACTERISTICS

INSTRUCTIONS: Complete A through J to determine whether you need to submit any permit application forms to the EPA. If you answer "yes" to any questions, you must submit this form and the supplemental form listed in the parenthesis following the question. Mark "X" in the box in the third column if the supplemental form is attached. If you answer "no" to each question, you need not submit any of these forms. You may answer "no" if your activity is excluded from permit requirements; see Section C of the instructions. See also, Section D of the instructions for definitions of bold-faced terms.

SPECIFIC QUESTIONS	MARK 'X'			SPECIFIC QUESTIONS	MARK 'X'		
	YES	NO	FORM ATTACHED		YES	NO	FORM ATTACHED
A. Is this facility a publicly owned treatment works which results in a discharge to waters of the U.S.? (FORM 2A)		X		B. Does or will this facility (either existing or proposed) include a concentrated animal feeding operation or aquatic animal production facility which results in a discharge to waters of the U.S.? (FORM 2B)		X	
C. Is this a facility which currently results in discharges to waters of the U.S. other than those described in A or B above? (FORM 2C)		X		D. Is this a proposed facility (other than those described in A or B above) which will result in a discharge to waters of the U.S.? (FORM 2D)		X	
E. Does or will this facility treat, store, or dispose of hazardous wastes? (FORM 3)	X		X	F. Do you or will you inject at this facility industrial or municipal effluent below the lowermost stratum containing, within one quarter mile of the well bore, underground sources of drinking water? (FORM 4)		X	
G. Do you or will you inject at this facility any produced water or other fluids which are brought to the surface in connection with conventional oil or natural gas production, inject fluids used for enhanced recovery of oil or natural gas, or inject fluids for storage of liquid hydrocarbons? (FORM 4)		X		H. Do you or will you inject at this facility fluids for special processes such as mining of sulfur by the Frasch process, solution mining of minerals, in situ combustion of fossil fuel, or recovery of geothermal energy? (FORM 4)		X	
I. Is this facility a proposed stationary source which is one of the 28 industrial categories listed in the instructions and which will potentially emit 100 tons per year of any air pollutant regulated under the Clean Air Act and may affect or be located in an attainment area? (FORM 5)		X		J. Is this facility a proposed stationary source which is NOT one of the 28 industrial categories listed in the instructions and which will potentially emit 250 tons per year of any air pollutant regulated under the Clean Air Act and may affect or be located in an attainment area? (FORM 5)		X	

III. NAME OF FACILITY

1 SKIP LEXINGTON LAMP PLANT

IV. FACILITY CONTACT

A. NAME & TITLE (last, first, & title)

2 A.C. BAYER

B. PHONE (area code & no.)

606 277 1161

V. FACILITY MAILING ADDRESS

A. STREET OR P.O. BOX

3 1801 GEDR.

B. CITY OR TOWN

4 LEXINGTON

C. STATE

KY

D. ZIP CODE

40503

VI. FACILITY LOCATION

A. STREET, ROUTE NO. OR OTHER SPECIFIC IDENTIFIER

5 1801 GEDR.

B. COUNTY NAME

AYETTE

C. CITY OR TOWN

LEXINGTON

D. STATE

KY

E. ZIP CODE

40503

F. COUNTY CODE (if known)



A. FIRST				B. SECOND			
C				C			
7	3	6	4	7			
15	16	-	19	15	16	-	19
(specify) Manufactur Electric Lamps				(specify)			
C. THIRD				D. FOURTH			
C				C			
7				7			
15	16	-	19	15	16	-	19
(specify)				(specify)			

A. NAME															B. Is the name listed in Item VIII-A also the owner?
8	GENERAL ELECTRIC CO.														<input checked="checked" type="checkbox"/> YES <input type="checkbox"/> NO

C. STATUS OF OPERATOR (Enter the appropriate letter into the answer box; if "Other", specify.)				D. PHONE (area code & no.)			
F = FEDERAL	M = PUBLIC (other than federal or state)	P	(specify)	C			
S = STATE	O = OTHER (specify)			A	6 0 6	2 7 7	1 1 6 1
P = PRIVATE				15	16 - 18	19 - 21	22 - 28

E. STREET OR P.O. BOX	
1801	GE. DR.


F. CITY OR TOWN										G. STATE		H. ZIP CODE		IX. INDIAN LAND	
LEXINGTON										KY		40503		Is the facility located on Indian lands? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	

A. NPDES (Discharges to Surface Water)										D. PSD (Air Emissions from Proposed Sources)									
C	T	I								S	T	I							
9	N		N O N E							9	P		N O N E						
15	16	17	18	19	20	21	22	23	24	15	16	17	18	19	20	21	22	23	24
B. UIC (Underground Injection of Fluids)										E. OTHER (specify)									
C	T	I								C	T	I							
9	U		N O N E							9			N O N E						
15	16	17	18	19	20	21	22	23	24	15	16	17	18	19	20	21	22	23	24
C. RCRA (Hazardous Wastes)										E. OTHER (specify)									
C	T	I								C	T	I							
9	R		N O N E							9			N O N E						
15	16	17	18	19	20	21	22	23	24	15	16	17	18	19	20	21	22	23	24

Attach to this application a topographic map of the area extending to at least one mile beyond property boundaries. The map must show the outline of the facility, the location of each of its existing and proposed intake and discharge structures, each of its hazardous waste treatment, storage, or disposal facilities, and each well where it injects fluids underground. Include all springs, rivers and other surface water bodies in the map area. See instructions for precise requirements.

Manufacture of sealed beam headlamps for automobiles

*I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attachments and that, based on my inquiry of those persons immediately responsible for obtaining the information contained in the application, I believe that the information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.*

A. NAME & OFFICIAL TITLE (type or print)	B. SIGNATURE	C. DATE SIGNED
H. J. SINGER, VICE PRESIDENT		11/14/80

# GENERAL ELECTRIC

MINIATURE  
LAMP  
DEPARTMENT

GENERAL ELECTRIC COMPANY, 1801 GE DRIVE, LEXINGTON, KENTUCKY 40503  
Phone (606) 277-1161

LEXINGTON LAMP PLANT

August 19, 1982

Mr. James H. Scarbrough  
U.S. Environmental Protection Agency  
345 Courtland Street N.E.  
Atlanta, Georgia 30365

Dear Mr. Scarbrough:


KYD 006386403

In April of this year, John Cory (General Electric) and Ms. Milly Archer (a Field Inspector with the Division of Waste Management, Field Operations Branch, Kentucky Department of Natural Resources and Environmental Protection) agreed in a phone conversation to withdraw the Hazardous Waste Facility application submitted to the U.S.E.P.A. and D.N.R.E.P.

Ms. Archer assured us that the withdrawal would be taken care of on the State and Federal levels with no further action on our part.

General Electric Lexington Lamp Plant stores hazardous waste in quantities less than 1000 kg for a time period of less than 90 days. We hereby request withdrawal of our Part A application (EPA Form 3510), thereby subjecting our plant to reduced requirements. If you have any further questions, please feel free to call.

Sincerely,

  
A. C. Bayer

Manager, Manufacturing Engineering

cc: Arthur Curtis  
Division of Waste Management

ACB/lsg



September 23, 1982

Mr. A.C. Bayer, Manager  
Manufacturing Engineer  
General Electric Company  
1801 G.E. Drive  
Lexington, Kentucky 40503

RE: EPA I.D. KYD00-638-6403

Dear Mr. Bayer:

The Division of Waste Management, acting under RCRA Phase I Interim Authorization (as published in the April 1, 1981, Federal Register), is withdrawing your U.S. EPA form 3510-1 known as the Federal Hazardous Waste Facility permit application part "A". The U.S. EPA has determined that your company can terminate their interim status as a storage facility without complying with 40 CFR Part 265 Subparts G and H, provided they continue to use the area for storage of hazardous waste which will be removed within the 90 day limit and are in compliance with 40 CFR 262.34. If your company no longer intends to use the area for storage of hazardous wastes, it must be closed in accordance with 40 CFR Part 265 Subpart G and H.

If you have any questions on this, please contact James A. Determann of this office at (502) 564-6716, Ext. 248.

Sincerely,



J. Alex Barber, Director  
Division of Waste Management

JAB:JAD:cg

cc: James H. Scarbrough, U.S. EPA  
Field Supervisor



FORM 3 RCRA		U.S. ENVIRONMENTAL PROTECTION AGENCY HAZARDOUS WASTE PERMIT APPLICATION Consolidated Permits Program (This information is required under Section 3005 of RCRA.)		I. EPA I.D. NUMBER F K Y D 0 0 6 3 8 6 4 0 3 1																																																																									
FOR OFFICIAL USE ONLY				COMMENTS																																																																									
APPLICATION APPROVED		DATE RECEIVED (yr., mo., & day)																																																																											
II. FIRST OR REVISED APPLICATION																																																																													
Place an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your facility or a revised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number in Item I above.																																																																													
A. FIRST APPLICATION (place an "X" below and provide the appropriate date)																																																																													
<input checked="" type="checkbox"/> 1. EXISTING FACILITY (See instructions for definition of "existing" facility. Complete item below.)																																																																													
<input type="checkbox"/> 2. NEW FACILITY (Complete item below.)																																																																													
FOR EXISTING FACILITIES, PROVIDE THE DATE (yr., mo., & day) OPERATION BEGAN OR THE DATE CONSTRUCTION COMMENCED (use the boxes to the left)																																																																													
B. REVISED APPLICATION (place an "X" below and complete Item I above)																																																																													
<input type="checkbox"/> 1. FACILITY HAS INTERIM STATUS																																																																													
<input type="checkbox"/> 2. FACILITY HAS A RCRA PERMIT																																																																													
III. PROCESSES - CODES AND DESIGN CAPACITIES																																																																													
A. PROCESS CODE - Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering codes. If more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes below, then describe the process (including its design capacity) in the space provided on the form (Item III-C).																																																																													
B. PROCESS DESIGN CAPACITY - For each code entered in column A enter the capacity of the process.																																																																													
1. AMOUNT - Enter the amount.																																																																													
2. UNIT OF MEASURE - For each amount entered in column B(1), enter the code from the list of unit measure codes below that describes the unit of measure used. Only the units of measure that are listed below should be used.																																																																													
<table border="1"><thead><tr><th>PROCESS</th><th>PRO-CESS CODE</th><th>APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY</th><th>PROCESS</th><th>PRO-CESS CODE</th><th>APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY</th></tr></thead><tbody><tr><td>Storage:</td><td></td><td></td><td>Treatment:</td><td></td><td></td></tr><tr><td>CONTAINER (barrel, drum, etc.)</td><td>S01</td><td>GALLONS OR LITERS</td><td>TANK</td><td>T01</td><td>GALLONS PER DAY OR LITERS PER DAY</td></tr><tr><td>TANK</td><td>S02</td><td>GALLONS OR LITERS</td><td>SURFACE IMPOUNDMENT</td><td>T02</td><td>GALLONS PER DAY OR LITERS PER DAY</td></tr><tr><td>WASTE PILE</td><td>S03</td><td>CUBIC YARDS OR CUBIC METERS</td><td>INCINERATOR</td><td>T03</td><td>TONS PER HOUR OR METRIC TONS PER HOUR</td></tr><tr><td>SURFACE IMPOUNDMENT</td><td>S04</td><td>GALLONS OR LITERS</td><td></td><td>T04</td><td>GALLONS PER HOUR OR LITERS PER HOUR</td></tr><tr><td>Disposal:</td><td></td><td></td><td>OTHER (Use for physical, chemical, thermal or biological treatment processes not occurring in tanks, surface impoundments or incinerators. Describe the processes in the space provided; Item III-C.)</td><td></td><td></td></tr><tr><td>INJECTION WELL</td><td>D79</td><td>GALLONS OR LITERS</td><td></td><td></td><td></td></tr><tr><td>LANDFILL</td><td>D80</td><td>ACRE-FEET (the volume that would cover one acre to a depth of one foot) OR HECTARE-METER</td><td></td><td></td><td></td></tr><tr><td>LAND APPLICATION</td><td>D81</td><td>ACRES OR HECTARES</td><td></td><td></td><td></td></tr><tr><td>OCEAN DISPOSAL</td><td>D82</td><td>GALLONS PER DAY OR LITERS PER DAY</td><td></td><td></td><td></td></tr><tr><td>SURFACE IMPOUNDMENT</td><td>D83</td><td>GALLONS OR LITERS</td><td></td><td></td><td></td></tr></tbody></table>						PROCESS	PRO-CESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY	PROCESS	PRO-CESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY	Storage:			Treatment:			CONTAINER (barrel, drum, etc.)	S01	GALLONS OR LITERS	TANK	T01	GALLONS PER DAY OR LITERS PER DAY	TANK	S02	GALLONS OR LITERS	SURFACE IMPOUNDMENT	T02	GALLONS PER DAY OR LITERS PER DAY	WASTE PILE	S03	CUBIC YARDS OR CUBIC METERS	INCINERATOR	T03	TONS PER HOUR OR METRIC TONS PER HOUR	SURFACE IMPOUNDMENT	S04	GALLONS OR LITERS		T04	GALLONS PER HOUR OR LITERS PER HOUR	Disposal:			OTHER (Use for physical, chemical, thermal or biological treatment processes not occurring in tanks, surface impoundments or incinerators. Describe the processes in the space provided; Item III-C.)			INJECTION WELL	D79	GALLONS OR LITERS				LANDFILL	D80	ACRE-FEET (the volume that would cover one acre to a depth of one foot) OR HECTARE-METER				LAND APPLICATION	D81	ACRES OR HECTARES				OCEAN DISPOSAL	D82	GALLONS PER DAY OR LITERS PER DAY				SURFACE IMPOUNDMENT	D83	GALLONS OR LITERS			
PROCESS	PRO-CESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY	PROCESS	PRO-CESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY																																																																								
Storage:			Treatment:																																																																										
CONTAINER (barrel, drum, etc.)	S01	GALLONS OR LITERS	TANK	T01	GALLONS PER DAY OR LITERS PER DAY																																																																								
TANK	S02	GALLONS OR LITERS	SURFACE IMPOUNDMENT	T02	GALLONS PER DAY OR LITERS PER DAY																																																																								
WASTE PILE	S03	CUBIC YARDS OR CUBIC METERS	INCINERATOR	T03	TONS PER HOUR OR METRIC TONS PER HOUR																																																																								
SURFACE IMPOUNDMENT	S04	GALLONS OR LITERS		T04	GALLONS PER HOUR OR LITERS PER HOUR																																																																								
Disposal:			OTHER (Use for physical, chemical, thermal or biological treatment processes not occurring in tanks, surface impoundments or incinerators. Describe the processes in the space provided; Item III-C.)																																																																										
INJECTION WELL	D79	GALLONS OR LITERS																																																																											
LANDFILL	D80	ACRE-FEET (the volume that would cover one acre to a depth of one foot) OR HECTARE-METER																																																																											
LAND APPLICATION	D81	ACRES OR HECTARES																																																																											
OCEAN DISPOSAL	D82	GALLONS PER DAY OR LITERS PER DAY																																																																											
SURFACE IMPOUNDMENT	D83	GALLONS OR LITERS																																																																											
<table border="1"><thead><tr><th>UNIT OF MEASURE</th><th>UNIT OF MEASURE CODE</th><th>UNIT OF MEASURE</th><th>UNIT OF MEASURE CODE</th><th>UNIT OF MEASURE</th><th>UNIT OF MEASURE CODE</th></tr></thead><tbody><tr><td>GALLONS</td><td>G</td><td>LITERS PER DAY</td><td>V</td><td>ACRE-FEET</td><td>A</td></tr><tr><td>LITERS</td><td>L</td><td>TONS PER HOUR</td><td>D</td><td>HECTARE-METER</td><td>F</td></tr><tr><td>CUBIC YARDS</td><td>Y</td><td>METRIC TONS PER HOUR</td><td>W</td><td>ACRES</td><td>B</td></tr><tr><td>CUBIC METERS</td><td>C</td><td>GALLONS PER HOUR</td><td>E</td><td>HECTARES</td><td>G</td></tr><tr><td>GALLONS PER DAY</td><td>U</td><td>LITERS PER HOUR</td><td>H</td><td></td><td></td></tr></tbody></table>						UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	GALLONS	G	LITERS PER DAY	V	ACRE-FEET	A	LITERS	L	TONS PER HOUR	D	HECTARE-METER	F	CUBIC YARDS	Y	METRIC TONS PER HOUR	W	ACRES	B	CUBIC METERS	C	GALLONS PER HOUR	E	HECTARES	G	GALLONS PER DAY	U	LITERS PER HOUR	H																																						
UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE																																																																								
GALLONS	G	LITERS PER DAY	V	ACRE-FEET	A																																																																								
LITERS	L	TONS PER HOUR	D	HECTARE-METER	F																																																																								
CUBIC YARDS	Y	METRIC TONS PER HOUR	W	ACRES	B																																																																								
CUBIC METERS	C	GALLONS PER HOUR	E	HECTARES	G																																																																								
GALLONS PER DAY	U	LITERS PER HOUR	H																																																																										
EXAMPLE FOR COMPLETING ITEM III (shown in line numbers X-1 and X-2 below): A facility has two storage tanks, one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.																																																																													
C. DUP																																																																													
LINE NUMBER																																																																													
A. PRO-CESS CODE (from list above)																																																																													
B. PROCESS DESIGN CAPACITY																																																																													
1. AMOUNT (specify)																																																																													
2. UNIT OF MEASURE (enter code)																																																																													
FOR OFFICIAL USE ONLY																																																																													
LINE NUMBER																																																																													
A. PRO-CESS CODE (from list above)																																																																													
B. PROCESS DESIGN CAPACITY																																																																													
1. AMOUNT																																																																													
2. UNIT OF MEASURE (enter code)																																																																													
FOR OFFICIAL USE ONLY																																																																													
X-1 S 0 2 600 G																																																																													
X-2 T 0 3 20 E																																																																													
1 S 0 1 1100 G																																																																													
2																																																																													
3																																																																													
4																																																																													



**III. PROCESSES (continued)**

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

**IV. DESCRIPTION OF HAZARDOUS WASTES**

**A. EPA HAZARDOUS WASTE NUMBER** — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.

**B. ESTIMATED ANNUAL QUANTITY** — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.

**C. UNIT OF MEASURE** — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS.....	P	KILOGRAMS.....	K
TONS.....	T	METRIC TONS.....	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

**D. PROCESSES****1. PROCESS CODES:**

For listed hazardous wastes: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item (1) to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item (1) to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

Notes: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

**2. PROCESS DESCRIPTION:** If a code is not listed for a process that will be used, describe the process in the space provided on the form.

**NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER** — Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

**EXAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below)** — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

LINE NO. X-1 X-2 X-3 X-4	A. EPA HAZARDOUS WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES	
				1. PROCESS CODES (enter)	2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	K 0 5 4	900	P	T 0 3 D 8 0	
X-2	D 0 0 2	400	P	T 0 3 D 8 0	
X-3	D 0 0 1	100	P	T 0 3 D 8 0	
X-4	D 0 0 2				included with above



Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)															FOR OFFICIAL USE ONLY												
W	K	Y	D	0	0	6	3	8	6	4	0	3	T/A	C	W	DUP					T/A	C	DUP				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26		

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

WASTE NO.	A. EPA HAZARD. WASTE NO. (enter code)				B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES									
	23	24	25	26			1. PROCESS CODES (enter)					2. PROCESS DESCRIPTION (if a code is not entered in D(1))				
1	F	0	0	1	13800	P	S	0	1							
2	U	0	4	3	20	P	S	0	1							
3	U	1	5	1	5	P	S	0	1							
4																
5																
6																
7																
8																
9																
10																
11																
12																
13																
14																
15																
16																
17																
18																
19																
20																
21																
22																
23																
24																
25																
26																

## IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM ITEM D(1) ON PAGE 3.

EPA I.D. NO. (enter from page 1)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
K	Y	D	0	0	6	3	8	6	4	0	3			

## V. FACILITY DRAWING

All existing facilities must include in the space provided on page 5 a scale drawing of the facility (see instructions for more detail).

## VI. PHOTOGRAPHS

All existing facilities must include photographs (aerial or ground-level) that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites of future storage, treatment or disposal areas (see instructions for more detail).

## VII. FACILITY GEOGRAPHIC LOCATION

LATITUDE (degrees, minutes, &amp; seconds)

38 01 19 N

LONGITUDE (degrees, minutes, &amp; seconds)

84 31 17 W

## VIII. FACILITY OWNER


☒ A. If the facility owner is also the facility operator as listed in Section VIII on Form 1, "General Information", place an "X" in the box to the left and skip to Section IX below.

B. If the facility owner is not the facility operator as listed in Section VIII on Form 1, complete the following items:

1. NAME OF FACILITY'S LEGAL OWNER				2. PHONE NO. (area code & no.)			
General Electric Company				606-277-1161			
3. STREET OR P.O. BOX				4. CITY OR TOWN		5. ST.	
1801 G.E. Drive				Lexington, KY		40503	

## IX. OWNER CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A. NAME (print or type)	B. SIGNATURE	C. DATE SIGNED
H. J. SINGER, VICE PRESIDENT		11/14/80

## X. OPERATOR CERTIFICATION


I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A. NAME (print or type)	B. SIGNATURE	C. DATE SIGNED



## V. FACILITY DRAWING (see page 4)

## GENERAL ELECTRIC COMPANY - LEXINGTON LAMP PLANT



APPROXIMATE SCALE:



# Part A, Permit Process --- Internal Checklist

ID Number KYD006386403 Inst Name GENERAL ELECTRIC CO.

## PHASE ONE

Refer to Form No:	Interim Regulatory Requirements	Indicate by your initials:		Valid Prm/g Date?
		Yes	No	
1	T/S/D Facility? (If No, return to respondent.)	<u>PK</u>	___	
3	Form 1 received?	<u>PK</u>	___	
1	Form 3 received?	<u>PK</u>	___	
1 & 3	Postmarked on or before November 19, 1980?	___	<u>PK</u>	<u>Nov/20</u>
3	Date of operation entered?	<u>PK</u>	___	
3	Date of operation on or before November 19, 1980?	<u>PK</u>	___	
Notif. record	Notifier?	<u>PK</u>	___	
"	Notified on or before August 18, 1980?	<u>PK</u>	___	
1	Form 1, XIII B signed?	<u>PK</u>	___	
3	Form 3, IX B Signed?	<u>PK</u>	___	

(If all ten items above are initialed in the Yes column, generate Interim Status Acknowledgement and indicate the trigger date here: \_\_\_\_\_)

## PHASE TWO

1	Unsure if regulated or non-regulated?	___	<u>PK</u>
3	New facility?	___	<u>PK</u>
1 & 3	Core items missing? If Yes, indicate which items: Facility name___; location___; mail address___; operator info___; certification___; process info___; waste info___; owner___; sigs <u>PK</u> .		

## PHASE THREE

1 & 3	Non-core items missing? If Yes, indicate which items: Maps___; photos___; drawings___; lat/long___. Other observations and comments:
-------	--

Log out/Log in  
on reverse side.

Received Date Stamp
NOV 20 1980
(Stamp forms also)



FORM 3 (EPA FORM 3510-3)

ITEM NUMBER

Missing

II. First Application

\*1. Existing Facility Date (on or before  
November 19, 1980)

☐

OR

\*2. New Facility Date (after November 19, 1980)

☐

III. Processes

\*A. Process Code

☐

\*B. Process Design Capacity-Amount

\*1. Amount

☐

\*2. Unit of Measure

☐

IV. Description of Hazardous Wastes

\*A. EPA Hazardous Waste Number

☐

\*B. Estimated Annual Quantity

☐

\*C. Unit of Measure

☐

\*D. Processes

\*1. Process Codes

☐

\*2. Process Description (If no code is shown)

☐

V. Facility Drawing

☐

VI. Photographs

☐

VII. Facility Geographic Location Latitude

Latitude

☐

Longitude

☐

Over

VIII. Facility Owner

- \*1. Name of Facility's Legal Owner
- 2. Phone
- \*3. Street or P.O. Box
- \*4. City or Town
- \*5. State
- 6. Zip Code


IX. Owner Certification

- \*A. Name
- \*B. Signature
- \*C. Date Signed


X. Operator Certification

- \*A. Name
- \*B. Signature
- \*C. Date

<del> </del>
<del> </del>
<del> </del>

Comments:




\*Form 3 is missing

--

GENERAL ELECTRIC COMPANY - LEXINGTON LAMP PLANT

9-10-80






LATITUDE 38° 01' 19"  
 LONGITUDE 84° 31' 17"

LOCATION MAP  
 GENERAL ELECTRIC COMPANY  
 LEXINGTON LAMP PLANT  
 FAYETTE COUNTY, KENTUCKY









UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IV

345 COURTLAND STREET  
ATLANTA, GEORGIA 30365

DEC 15 1980

REF: 4E-WE

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Merge Active

KYD 006386403

General Electric Company  
1801 G E Drive  
Lexington, KY 40503

Re: Section 3007, Resource Conservation and  
Recovery Act (RCRA). Request for Information.

Dear Sir:

Your organization has been identified by the Environmental Protection Agency as one which probably handles hazardous wastes. The generation, transportation, treatment, storage and disposal of such wastes are regulated by the Resource Conservation and Recovery Act of 1976 (RCRA), 42 U.S.C. §6901 et seq., as amended by the Solid Waste Disposal Act Amendments of 1980. Under authority of the Act, on May 19 and at various times thereafter, the U. S. Environmental Protection Agency published in the Federal Register regulations listing certain waste as hazardous and specifying characteristics to be used in determining whether nonlisted wastes are hazardous (45 F.R. 33066). Under Section 3010 of the Act, handlers of hazardous wastes identified in the May 19, 1980 regulations were required to notify EPA by August 18, 1980. Handlers of waste identified in later publications had until 90 days after each publication within which to notify.

In May, informational packets containing notification material were sent to over 400,000 organizations thought to be handlers of hazardous wastes. However, failure to receive such a packet did not relieve a hazardous waste handler of its legal obligation to notify EPA of its activities. If you are indeed a handler of hazardous waste identified in the May 19 regulations, your notification was due on August 18.

In order that we may determine whether your failure to notify was proper, it is requested, pursuant to Section 3007 of the Act, that you complete the attached questionnaire and return it within ten (10) days to the address indicated.



Return to:

Environmental Protection Agency  
Compliance Section, Enforcement Division  
345 Courtland Street  
Atlanta, Georgia 30365

Section 3007 RCRA Questionnaire

1. If you have previously notified, please indicate I.D.  
No. KYD006386403 and disregard items 2 through 6.
2. Do you generate, transport, treat, store or dispose or any  
hazardous waste identified in 40 CFR Part 261, Subparts A,  
B, C, and D (45 FR 33119)?  
Yes \_\_\_\_; No \_\_\_\_; Don't Know \_\_\_\_  
Please send a Notification Form 8700-12. \_\_\_\_
3. Describe the nature of your business. \_\_\_\_\_  
\_\_\_\_\_
4. What waste products do you handle? \_\_\_\_\_  
\_\_\_\_\_
5. What quantity of each waste do you handle?  
\_\_\_\_\_ lbs/month \_\_\_\_\_ lbs/year  
or \_\_\_\_\_ kg/month \_\_\_\_\_ kg/year
6. What do you do with these wastes? \_\_\_\_\_  
\_\_\_\_\_

Monica D. Williams 12/18/80  
Signature Date

Manager Lexington Lamp Plant  
Title

G.E. Lexington Lamp Plant  
Company Name

1801 G.E. Drive P.O. Box 8053  
Address

Lexington, KY 40503

✓cw

# NOTIFICATION OF HAZARDOUS WASTE ACTIVITY

**INSTRUCTIONS:** If you received a preprinted label, affix it in the space at left. If any of the information on the label is incorrect, draw a line through it and supply the correct information in the appropriate section below. If the label is complete and correct, leave Items I, II, and III below blank. If you did not receive a preprinted label, complete all items. "Installation" means a single site where hazardous waste is generated, treated, stored and/or disposed of, or a transporter's principal place of business. Please refer to the INSTRUCTIONS FOR FILING NOTIFICATION before completing this form. The information requested herein is required by law (Section 3010 of the Resource Conservation and Recovery Act).

INSTALLATION'S EPA I.D. NO.

I. NAME OF INSTALLATION

II. INSTALLATION MAILING ADDRESS

III. LOCATION OF INSTALLATION

KYD006386403

KYD006386395

GENERAL ELECTRIC CO.  
PO BOX 8053  
LEXINGTON, KY 40503

1801 GE DRIVE  
PO BOX 8053  
LEXINGTON, KY 40503

RECEIVED  
EPA/REGION I

SEP 10 1 46 PM '81

ENTERED IN

FOR OFFICIAL USE ONLY

COMMENTS

INSTALLATION'S EPA I.D. NUMBER

APPROVED

DATE RECEIVED (yr., mo., & day)

KYD006386403

T/A C

80 CB 18

I. NAME OF INSTALLATION

GE LEXINGTON LAMP PLANT

II. INSTALLATION MAILING ADDRESS

STREET OR P.O. BOX

31801 GE DR BOX 8053

CITY OR TOWN

4 LEXINGTON

ST.

ZIP CODE

III. LOCATION OF INSTALLATION

STREET OR ROUTE NUMBER

51801 GE DRIVE

CITY OR TOWN

6 LEXINGTON

ST.

ZIP CODE

IV. INSTALLATION CONTACT

NAME AND TITLE (last, first, & job title)

2 BAYER A MANAGER MANU ENG

PHONE NO. (area code & no.)

606-277-1161

A. NAME OF INSTALLATION'S LEGAL OWNER

8 GENERAL ELECTRIC COMPANY

VI. TYPE OF HAZARDOUS WASTE ACTIVITY (enter "X" in the appropriate box(es))

☒ A. GENERATION

☐ B. TRANSPORTATION (complete item VII)

☒ C. TREAT/STORE/DISPOSE

☐ D. UNDERGROUND INJECTION

B. TYPE OF OWNERSHIP (enter the appropriate letter into box)

M

F = FEDERAL  
M = NON-FEDERAL

VII. MODE OF TRANSPORTATION (transporters only - enter "X" in the appropriate box(es))

☐ A. AIR

☐ B. RAIL

☐ C. HIGHWAY

☐ D. WATER

☐ E. OTHER (specify):

III. FIRST OR SUBSEQUENT NOTIFICATION

Mark "X" in the appropriate box to indicate whether this is your installation's first notification of hazardous waste activity or a subsequent notification. If this is not your first notification, enter your Installation's EPA I.D. Number in the space provided below.

☒ A. FIRST NOTIFICATION

☐ B. SUBSEQUENT NOTIFICATION (complete item C)

C. INSTALLATION'S EPA I.D. NO.

DESCRIPTION OF HAZARDOUS WASTES

Use go to the reverse of this form and provide the requested information.

CONTINUE ON REVERSE



9	W	K	D	0	0	6	3	8	6	4	0	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15

# **IX. DESCRIPTION OF HAZARDOUS WASTES (continued from front)**

**A. HAZARDOUS WASTES FROM NON-SPECIFIC SOURCES.** Enter the four-digit number from 40 CFR Part 261.31 for each listed hazardous waste from non-specific sources your installation handles. Use additional sheets if necessary.

1 F 0 0 1 23 - 26 7 23 - 26	2 23 - 26 8 23 - 26	3 23 - 26 9 23 - 26	4 23 - 26 10 23 - 26	5 23 - 26 11 23 - 26	6 23 - 26 12 23 - 26
---	------------------------------	------------------------------	-------------------------------	-------------------------------	-------------------------------

**B. HAZARDOUS WASTES FROM SPECIFIC SOURCES.** Enter the four-digit number from 40 CFR Part 261.32 for each listed hazardous waste from specific industrial sources your installation handles. Use additional sheets if necessary.

13 U 0 4 3 23 - 26 19 23 - 26 25 23 - 26	14 U 1 5 1 23 - 26 20 23 - 26 26 23 - 26	15 23 - 26 21 23 - 26 27 23 - 26	16 23 - 26 22 23 - 26 28 23 - 26	17 23 - 26 23 23 - 26 29 23 - 26	18 23 - 26 24 23 - 26 30 23 - 26
--	--	---	---	---	---

**C. COMMERCIAL CHEMICAL PRODUCT HAZARDOUS WASTES.** Enter the four-digit number from 40 CFR Part 261.33 for each chemical substance your installation handles which may be a hazardous waste. Use additional sheets if necessary.

31 23 - 26 37 23 - 26 43 23 - 26	32 23 - 26 38 23 - 26 44 23 - 26	33 23 - 26 39 23 - 26 45 23 - 26	34 23 - 26 40 23 - 26 46 23 - 26	35 23 - 26 41 23 - 26 47 23 - 26	36 23 - 26 42 23 - 26 48 23 - 26
---	---	---	---	---	---

**D. LISTED INFECTIOUS WASTES.** Enter the four-digit number from 40 CFR Part 261.34 for each listed hazardous waste from hospitals, veterinary hospitals, medical and research laboratories your installation handles. Use additional sheets if necessary.

49 23 - 26	50 23 - 26	51 23 - 26	52 23 - 26	53 23 - 26	54 23 - 26
---------------	---------------	---------------	---------------	---------------	---------------

**E. CHARACTERISTICS OF NON-LISTED HAZARDOUS WASTES.** Mark "X" in the boxes corresponding to the characteristics of non-listed hazardous wastes your installation handles. (See 40 CFR Parts 261.21 - 261.24.)

☒ 1. IGNITABLE  
(D001)

☒ 2. CORROSIVE  
(D002)

☐ 3. REACTIVE  
(D003)

☒ 4. TOXIC  
(D000)

## **X. CERTIFICATION**

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

SIGNATURE


NAME & OFFICIAL TITLE (type or print)

DATE SIGNED

PLANT MANAGER

7/9/80





GENERAL ELECTRIC CO. - LEXINGTON  
LAMP PLANT HAZARDOUS WASTE STORAGE  
AREA 10-29-80